

# Milling Circuit Boards with CircuitPro and S63 LPKF Machine

Instituto Tecnológico de Morelia  
Maestría en Ciencias en Ingeniería Electrónica  
"José María Morelos y Pavón"

June 17, 2018

# Índice

- 1** Machine Setup
  - The tool magazine
  - CAD systems
- 2** The CircuitPRO GUI
- 3** How to create a new project
  - Project stages
  - How many layers
  - Substrate
  - Layer files
    - The Layers
    - The Drill Layers
    - Contour router layer
    - Global Process Settings
  - Board production

# Machine Setup




Figure: Hardware configuration






Figure: Tool selection window

# Milling and Drilling Tools










Figure: CAD Software Selection



# Machine Setup The CircuitPRO GUI How to create a new project

## GUI




Figure: The CircuitPro Graphic User Interface

## Project stages

Once the machine has been configured, most of the PCBs follow the next process:

- Load a template project (**Single Side, Double Side, ...**)
- Import the **Gerber** files
- Create the tool-paths and link the tools
- Board Production

Machine Setup  
The CircuitPRO GUI  
How to create a new project

Project stages  
How many layers  
Substrate  
Layer files  
Board production




Figure: Load default template




Figure: Layers on board selection




Figure: Material selection

Machine Setup  
The CircuitPRO GUI  
How to create a new project

- Project stages
- How many layers
- Substrate
- Layer files
- Board production




Figure: Layer files importing

## Allowed files




Figure: Supported files

The file extension depends on the CAD software used. For Altium, the layers generated are the KeepOut, Bottom Layer and Top Layer, respectively (\*.GKO, \*.GBL y \*.GTL).



## Bottom layer




Figure: Bottom layer file




Figure: Top layer file

## The Drill Layers





Figure: Drill layer importing

# Capas de corte



# Machine Setup The CircuitPRO GUI How to create a new project


Project stages  
How many layers  
Substrate  
Layer files  
Board production

The screenshot displays the CircuitPRO CAM software interface. The main workspace shows a PCB layout on a red substrate. The layout includes a central component footprint with several traces extending to the left, where they terminate at five circular pads. Two larger circular pads are also visible on the left and right sides of the board. The text "CircuitPRO" is printed in a stylized font at the bottom of the board. The interface includes a menu bar (File, Edit, Insert, Toolpath, Modify, View, Select, Wizards, Machining, Extras, Help), a toolbar, and a Layers panel on the left. The Layers panel lists various layers with checkboxes for visibility and settings for color and mode. A navigation pane is located at the bottom left, and a fault monitor table is at the bottom right.

Name	Vis	Set	Color	Mode
Substrate (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
DrillPlated (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
DrillUnplated (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
MinConduct (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
ColdenPasteTop (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
ColdenMaskTop (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
TopLayer (M)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
ScrapTop (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
Subcutoff (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Outline	
BoardOutline (M)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Thin Line	
ProfileOutline (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Thin Line	
SubcutoffOutline (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Outline	
ProfileOutline (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
BottomLayer (M)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
ColdenMaskBottom (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
ColdenPasteBottom (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	
SubConductBottom (S)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	True Width	

Client ID	Client Description	Unit ID	Unit Description	Fault ID	Fault Time	Fault Code	Fault Description	Accept time
-----------	--------------------	---------	------------------	----------	------------	------------	-------------------	-------------

# Global Process Settings



The screenshot shows a 'Computation Results' dialog box with a blue header and a close button (X) in the top right corner. The main content area is titled 'Warnings' and contains a tree view under 'Drilling'. There are four warning entries, each with a yellow warning icon and a downward arrow. Each entry consists of an attention message, a size and object count, and an 'Assign these toolpaths to...' dropdown menu. The first entry is for 1.3 mm (2 objects) with 'Spiral Drill 0,7 mm' selected. The second is for 0.55 mm (1 object) with '<Please select tool... >' selected. The third is for 1.016 mm (29 objects) with '<Please select tool... >' selected. The fourth is for 1.194 mm (4 objects) with '<Please select tool... >' selected. To the right of the list are three buttons: 'Calculate' (blue), 'Save...' (grey), and 'Print...' (grey). At the bottom of the dialog is a 'Show more' button. A scrollbar is visible on the right side of the list.

**Computation Results**

**Warnings**

- Drilling**
  - Attention, no appropriate tools available to process 1.3 mm (2 objects have been ignored)  
Assign these toolpaths to...  
Spiral Drill 0,7 mm
  - Attention, no appropriate tools available to process 0.55 mm (1 objects have been ignored)  
Assign these toolpaths to...  
<Please select tool... >
  - Attention, no appropriate tools available to process 1.016 mm (29 objects have been ignored)  
Assign these toolpaths to...  
<Please select tool... >
  - Attention, no appropriate tools available to process 1.194 mm (4 objects have been ignored)  
Assign these toolpaths to...  
<Please select tool... >

Calculate

Save...

Print...

Show more

Until this point, every parameter on the PCB design was configured. Thus, the next step is to prepare the board production with the board production wizard from CircuitPro. This will guide through the production process and its necessary steps.






Figure: Board Production Wizard

Board Production Wizard


CircuitPro

LPKF  
Laser & Electronics

### Mount material

**Overview**

- Mount material
- Material settings
- Placement
- Drill fiducial
- Marking drills
- Drilling plated
- Drilling unplated
- Milling layer 'TextBott...
- Milling bottom layer
- Bottom 2.5D milling i...
- Flip material
- Read fiducials on top ...



Mount the base material with an underlay plate underneath onto the processing area and affix it with adhesive tape.

Start Cancel

**Material Settings**

Application

PCB  
 Front panel/Engraving (2.5D)

Properties

Material Type: FR4

Copper Thickness [µm]: 18.0

Material thickness: 0.46 mm

Underlay plate thickness: 2 mm

Location

Click into the machine area to move the active head to the associated position.

Use the buttons to set the front left and right rear corner of the material.

Please make sure that the working-depth limiter of the machine head does not touch the tape used to fix the material.

Current head position

X: 0 mm

Y: 325 mm

Z: 0 mm


Material width: 305 mm

Material length: 229 mm

Surface level [0]: <undefined>

Material corners [mm]: (12.50 / 2.50) : (317.50 / 231.50)

Continue Close Abort





## Tool Exchange

Please remove the loaded tool and insert the following tool: **Universal Cutter 0,2 mm**

Click OK to continue without milling width adjustment.

Click Milling Width to adjust the milling width before milling.

Click Cancel to abort the production process.

OK

Milling Width

Cancel

